

Doors & Grilles X2, X4 and Vector[™] Unit

From Baseball Bats to Corrosive Attacks, Our Doors Stood Up to Everything We Threw at Them

High Strength & Durability

- Twin-sheet composite panel construction provides superior structural integrity
- Enhanced impact resistance vs. ABS and fiberglass options
- Whether below freezing or in the desert heat, the doors maintain thermal stability and impact resistance
- Withstands common impacts like trees and branches

Aesthetics

- Proprietary blend top-coat delivers an impervious colorfast finish that lasts
- UV light resistance protects against sun fading
- Repels dirt and moisture
- Easy to clean
- Chemical and scratch resistant

Sound Quality

- Aero-acoustic grille
- Integrated door seals

Made in the U.S.A.



DuraShell[™] 2 Doors:*

- ✓ Superior structural integrity
- ✓ 200% higher impact strength
- ✓ 50% better thermal stability
- ✓ 20% higher temperature resistance
- ✓ 100% better UV resistance
- Impregnated color
- Lighter weight
- ✓ Proven reliability in the transportation environment

*Carrier Transicold X2, X4 and Vector unit (excluding Vector 1800) doors vs. prior generation unit doors.

www.carrier.com/performance-parts

DuraShell[™] 2 Replacement Doors and Grilles

Made from the latest composite materials, Carrier Transicold's high-strength colorfast replacement doors and grilles repel dirt, damage and UV rays.



Replacement doors used on Carrier Transicold X2, X4 and Vector units (excluding Vector 1800). Unit shown with chrome grille/latch option.

Replacement Latch Assemblies

- Two-stage locking mechanism for added security
- Single release for service access
- · Self-aligning latch-pin design

Part Number	Description
44-00443-00	Roadside – Black
44-00443-02	Roadside – Chrome
44-00443-01	Curbside – Black
44-00443-03	Curbside – Chrome

North America Carrier Transicold 700 Olympic Drive Athens, GA 30601 USA Central America and Mexico Carrier Transicold Ejercito Nacional 253-A Piso 5 Colonia Anahuac 11320 Mexico D.F.

